MODE COM IMPULS POWER SUPPLY INSTRUCTION MANUAL

1. INSTALLATION OF THE POWER SUPPLY

Step 1:
Unplug every power plug from the computer.

Step 2:
Take the case off the computer.

Step 3:
Disconnect all power connectors of the current power supply.

Step 4:
Unscrew four mounting screws at the back of the computer which fix the power supply to the computer case.

Step 5:
Screw on the new power supply to the computer case.

Step 6:
Connect the connectors of the new power supply to appropriate devices inside the computer.

! WARNING !
The connectors of the power supply are adjusted to be assembled only in particular way. If any problems with connecting occur turn round the connector and try again.

Step 7:
Make sure that all of the bolts have been properly screwed inside the computer. Short circuit may be caused by a falling screw.

Step 8:
Put on and mount the computer case.

Step 9:
Plug in the plug of the power cord.

2. WARNINGS

- **UNDER NO CIRCUMSTANCES SHOULD YOU OPEN THE COVER OF THE POWER SUPPLY.**
- **Damages to the seal on the device result in loss of right to warranty.**
- **Avoid exposing the device to the environment with increased humidity.**

3. TROUBLESHOOTING

If the power supply does not work carefully check:

- if the power cord is properly plugged to the power supply and if the switch on the power supply or the strip is on
- if all output connectors are properly connected to the devices inside the computer
- if un-plugging the power supply and plugging it again helps to regain proper operation

If the power supply does not work properly although above actions have been performed, please contact with sales representative of the producer to have the power supply fixed or replaced. Further information on our web side www.modecom.eu



WE EXPRESS THANKS AND CONGRATULATE YOU ON BEST CHOICE AVAILABLE

THE BEST SOLUTION IN POWER SUPPLYING!

MODE COM